



nv/sa

Advanced Aerospace Designs

Brussels, 7 March 2012

VIGIL INFORMATION BULLETIN: VIGIL LCD Software version 2.20

IDENTIFICATION:

All Vigil LCD's with LCD software version 2.20 mounted on Vigil serial numbers 23.350 – 24.970.

The LCD software version can be located during the startup sequence, in the INFO menu.

ORIGIN:

An interruption can occur on Vigils with LCD software version 2.20, resulting in a freezing or locking of the LCD screen.

ACTION:

Replacing the LCD at the next reserve repack cycle is advised.

If your LCD controller freezes, it should be replaced before the next jump.

LOGISTIC:

If your Vigil is affected by this notice, please contact your dealer or service@vigil.aero, or candace@vigil.aero (for USA, Canada and South America) with the serial number of your Vigil.

We will verify if your unit needs to be changed, and will send a free replacement LCD if needed.

REMARKS:

This issue can occur prior to the self-test and in this case, the unit is not switched on.

In some cases, this can occur immediately after landing.

If your 2.20 LCD controller has already been replaced, this information bulletin does not apply to you.



AAD nv/sa. Advanced Aerospace Designs - Belgium - Formerly: Bristol Babcock Benelux nv/sa

193, Bld. A. Reyers • B-1030 Brussels • T: +32 (0)2 732 65 52 • F: +32 (0)2 736 06 27 • info@vigil.aero • www.vigil.aero
V.A.T.: BE 0428.488.590 • R.C.B.: 477955 • Bank: Fortis 210-0624852-30 • Swift: GE BA BE BB 36A • IBAN Code: BE15 2100 6248 5230